
G-Wagen, W463, Water in Front Footwell Repair




If the internal polythene sheet has become dis-attached from the door surround, water will enter the car

© 2015 AF Page 1 of 13





© 2015 AF Page 2 of 13





© 2015 AF Page 3 of 13





© 2015 AF Page 4 of 13





© 2015 AF Page 5 of 13





© 2015 AF Page 6 of 13






© 2015 AF Page 7 of 13






© 2015 AF Page 8 of 13







© 2015 AF Page 9 of 13





© 2015 AF Page 10 of 13





© 2015 AF Page 11 of 13





© 2015 AF Page 12 of 13

Now, replace parts on reverse order.

© 2015 AF Page 13 of 13